


- A. Checking Stern Drive Unit Seawater Pickup Pump Output - MerCruiser I Stern Drives
- B. Insufficient Water Flow From MC-I Drive Unit Seawater Pickup Pump Troubleshooting Chart
- C. MC-I Drive Shaft Housing Water Passage Improperly Drilled

A. CHECKING STERN DRIVE UNIT SEAWATER PICKUP PUMP OUTPUT - MERCUISER I STERN DRIVES

The following test can be used when troubleshooting an overheating condition to determine if cause is due to insufficient water flow from seawater pickup pump in drive unit.

IMPORTANT: The following information should be observed before proceeding with test:

- **BOAT MUST BE IN THE WATER FOR THIS TEST.** This test **CANNOT BE** performed with a flush-test device and a water hose.
 - The ability of this test to detect a problem is greatly dependent upon the accuracy in which it is performed. An error in setting the engine RPM, timing the test or measuring the water output will affect the overall accuracy of the test and may produce misleading results. To help ensure accurate results, a shop tachometer with an error of less than 5% should be used. The boat tachometer definitely should not be used as its accuracy is questionable. A stop watch should be used to time the duration of the test to help ensure that the accuracy is maintained within 1 second. A 6 quart (or larger) capacity container calibrated in ¼ quart increments should be used to measure water output.
 - Due to the manner in which this test is performed, it may not be possible to detect a marginal condition or a high-speed water pump output problem. If test results are questionable or if adequate output is indicated but cause for overheating condition cannot be found, refer to the troubleshooting chart, following, and check the items indicated.
1. Remove water inlet hose, which runs between gimbal housing water tube and engine (Figure 1), and replace with another hose of same diameter, but approximately 3 ft. (91.4cm) longer. Hose should be wire reinforced or of adequate wall thickness to prevent it from kinking when performing test. Clamp hose at gimbal housing water tube only. Do not clamp hose at engine end.



a - Water Inlet Hose
b - Hose Clamp
c - Gimbal Housing Water Tube

Figure 1. Water Inlet Hose (Typical)

- Place a 6 quart (5.7 liter) or larger container near unclamped end of hose.

CAUTION: Do not run engine for more than 15 seconds with hose disconnected, in next step, as internal damage to engine and exhaust system may result.


- With the assistance of another person, start engine and adjust speed to exactly 1000 RPM, while holding unclamped end of hose on connection on engine. Remove hose from connection on engine and direct water flow into container for EXACTLY 15 seconds. At the end of 15 seconds, direct the water flow overboard, return engine to idle and stop engine. Reconnect hose to engine.
- Measure quantity of water discharged into container and compare with specifications given in chart below.

MINIMUM PUMP OUTPUT FOR 15 SECOND PERIOD	
Drive Unit Gear Ratio	Minimum Quantity
1.98:1	3.0 Qts. (2.8 liters)
1.84:1	3.3 Qts. (3.1 liters)
1.65:1	3.6 Qts. (3.4 liters)
1.50:1	4.0 Qts. (3.8 liters)
1.32:1	4.5 Qts. (4.3 liters)


- Repeat test 4 times to check repeatability of results.
- If output is insufficient, refer to troubleshooting chart, following.

B. INSUFFICIENT WATER FLOW FROM MC-I STERN DRIVE UNIT SEAWATER PICKUP PUMP TROUBLESHOOTING CHART

The following troubleshooting chart should be of assistance when troubleshooting an overheating condition due to insufficient water flow from seawater pickup pump in drive unit. Possible causes are arranged by those which are easiest to check to those which are most difficult.



continued page 3




C. MC-I DRIVE SHAFT HOUSING WATER PASSAGE IMPROPERLY DRILLED

If troubleshooting an otherwise unexplainable overheating condition, problem may be due to an improperly cross-drilled water passage in drive shaft housing. (Figure 2) A few cases have been reported where the drill was not run far enough into the water passage during the machining operation at the factory. Only the tip of the drill penetrated thru the casting at the end of the water passage, leaving a ¼" to ⅜" (6.4mm to 9.5mm) diameter hole [instead of a .580" (14.7mm) diameter hole] at end of passage. This restricted water flow sufficiently to cause engine to overheat.


To check cross-drilled water passage, remove stern drive unit and inspect passage thru water cavity on port (left) side of drive shaft housing (Figure 2), using a flashlight. Water passage should be approximately ½" (12.7mm) in diameter. If not, proceed as follows:

1. Remove decal from starboard (right) side of drive shaft housing and remove welch plug (under decal). (Figure 3)
2. Apply heat to water passage pipe plug (Figure 3) and remove plug with a large blade screwdriver.
3. Drill out material at end of water passage, using a 9/16" (14mm) diameter drill bit.
4. Clean threads in drive shaft housing with a ⅜" x 18 NPTF tap. Clean old sealer from pipe plug with a wire brush.
5. Apply Perfect Seal (92-34227) to threads of pipe plug and thread into drive shaft housing. PIPE PLUG MUST BE INSTALLED FLUSH OR SLIGHTLY INDENTED INTO INNER SURFACE OF DRIVE SHAFT HOUSING TO PREVENT INTERFERENCE WITH SHIFTING SLIDE ASSEMBLY.
6. Apply Loctite "A" (92-32609) to outer diameter of NEW welch plug (19-32562). Place plug in drive shaft housing and flatten, using a hammer and suitable driver.
7. Install a new decal.
8. Reinstall stern drive unit.



- a - Welch Plug
- b - Pipe Plug
- c - Water Passage
- d - Inspect Water Passage Thru This Cavity
- e - Passage MUST BE .580" (14.7mm) In Diameter

Figure 2. Drive Shaft Housing Cross-Drilled Water Passage



- a - Decal
- b - Welch Plug
- c - Pipe Plug

Figure 3. Cross-Drilled Water Passage Pipe Plug