

Service Bulletin

Bulletin No. 2016-02R1

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Trim Cylinder End Cap and Anode Installation

NOTICE	
Revised April 2016. This bulletin supersedes the previous bulletin number 2016-02 March 2015.	

Models Affected


Models Covered	Serial Number Or Year
Alpha Gen II	All
Bravo One, Bravo Two, Bravo Three	All

Scope

Worldwide

Situation


Interference between the anode mounting face and the end cap rod scraper may occur when installing anodes on end caps included in trim cylinder end cap kits 8M0110717 and 8M0115362.



Bravo cylinder

a - Anode

b - Interference area



Alpha cylinder

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Correction

Inspect the anode mounting face before installation. If the anode has a chamfered edge then no further action is necessary.


The anode modification described in this bulletin only applies to Alpha or Brave anodes that do not have a chamfered edge.

The anode modification described in this bulletin only applies to Alpha or Bravo anodes that do not have a chamfered edge when used with end caps included in end cap kits 8M0110717 and 8M0115362.

Create a 0.13" x 45° tapered chamfer on the edge of the inside diameter of the trim cylinder anode mounting face to prevent interference when installing end caps included in end cap kits 8M0110717 and 8M0115362.



Bravo anode with chamfer



Alpha anode with chamfer

NOTE: End caps with protruding rod scrapers were also used during factory production on Bravo SeaCore transom assemblies starting with serial number 2A480244, and standard Bravo transom assemblies starting with serial number 2A485656. Perform the chamfering procedure described in this bulletin when replacing trim cylinder anodes on these units if the end cap has a protruding rod scraper.



- a End cap
- b Protruding rod scraper

Warranty

United States and Canada: Mercury Marine will credit the dealer for the cost of the labor. Submit a warranty claim through your normal warranty-processing channel, listing:

Engine serial number

Labor: 0.20 hourFlat rate code: SB02Part code: 105Fail code: 00

Please contact Technical Service at (920) 929-5884 for a preauthorized claim if the engine is out of warranty.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Page 2 / 2 © 2016 Mercury Marine APRIL 2016 2016-02R1