

Revised 7-14-97

## Special Adjustment for Stator Failures - 40 thru 120, Sport Jet 90/120

### NOTICE

This is a revision of Force Outboard Service Bulletin 97-4. Destroy Bulletin 97-4 and insert this revised Bulletin 97-4 7-14-97. Changes are underlined.

### Models Affected

#### FORCE

1994 and 1995  
40/50 HP S/N OE032000 thru OE138599  
70 HP S/N OE032000 thru OE138599  
90/120 HP S/N OE032000 thru OE138599


#### SPORT JET

1994 and 1995  
Sport Jet 90 S/N OE033711 thru OE141088

1995  
Sport Jet 120 S/N OE093700 thru OE141088

The above listed models have experienced a higher than normal incidence of stator failures. The "red" stator was introduced with design improvements for increased reliability and durability. These models were manufactured prior to the installation of the red stator. If a stator failure occurs within the affected serial number range, Mercury Marine will cover parts and labor for three years from the original outboard date of sale. This applies to first and second owners. The bill of sale must be provided if the consumer is not the registered owner. Both pleasure and commercial use will be covered.

Failures of Quicksilver replacement stators purchased for use on the above listed models will be covered for three years from the replacement stator date of sale. Submit a paper warranty claim with a dated receipt of the failed stator.



### Warranty

Stator failures will be covered by a special warranty for three years from the original date of sale to assure customer satisfaction.

Complete Midas or Paper warranty claim:

- Serial number
- Qty. 1 (P/N ) Stator
- One and one half (1.5) hour labor
- Labor Rate Code:
 

Outboard	OA18	.5 hour
	OA15	1 hour
Sport Jet	JA18	.5 hour
	JA15	1 hour
- Failure Code: 323-00

**USA and Canada:** Tag and hold parts for 60 days after the warranty credit is received.

**International:** Hold failed stators for inspection/disposition by a Marine Power International technical representative.