

Service Bulletin

Bulletin No. 2009-07

| Circulate to: | Sales Manager | ☐ Accounting | Service Manager | Technician | Parts Manager |
|---------------|---------------|--------------|-----------------|------------|---------------|

Throttle Roller No Longer Available (NLA) (2.5 Liter OptiMax XS and 3.0 Liter EFI/OptiMax)

Models Affected

| Models Covered | Serial Number |
|---------------------------|-------------------|
| 200 XS 2.5 Liter OptiMax | 0T235000-0T818180 |
| 200/225 3.0 Liter OptiMax | 0T178500-0T800999 |
| 200/225/250 EFI 3.0 Liter | 0T409000-0T800999 |
| 300 X EFI 3.0 Liter | 0T235084-0T429939 |
| 3.0 Liter Sport Jet DFI | 0E407100-Up |

Situation

Throttle roller P/N 67748 3 is no longer available (NLA). This roller has been replaced with throttle roller and lever assemblies listed below.



40827

Throttle roller and lever assembly

| Description | Part Number |
|-------------|-------------|
| 2.5 Liter | 850286A03 |
| 3.0 Liter | 858851A03 |

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.