

Bulletin No. 2010-62 CMD 2010-02

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

# QSD 2.0L, 2.8L & 4.2L Service Manual Correction: Battery Isolator

# Models Affected

Models Affected	Serial Numbers
QSD 2.0L, 2.8L, and 4.2L	All

### Situation

Section 4B - Charging System of the following service manuals contain incorrect statements regarding the use of battery isolators:

Service Manual	Part Number
SM #47 QSD 2.8L and 4.2L Engines	90-866941
SM #48 QSD 2.0L Engines	90-866942

The second paragraph of the **Battery Isolators** procedure on page 4B-5 of both service manuals incorrectly states, "The alternators used on Cummins MerCruiser Diesel products are equipped with a special external sensing circuit..."

### Correction

The incorrect sentence on page 4B-5 of both service manuals should state, "In cases where the alternator does not have this feature, follow the instructions provided by the manufacturer of the battery isolator. Alternators used on Cummins MerCruiser Diesel QSD products are not equipped with an external sensing circuit..."

# Parts

None required.

### Warranty

Not applicable.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.