

# service bulletin



No. 91-3

## **New Style Piston Pin Lock Rings**

### **MODELS**


1991 M.H.P. 2.5 Carb/2.5 EFI/ 2.5 EFI Offshore

#### **CHANGES**

New syle piston pin lock rings.

### **EXPLANATION**

The new style lock rings have an anti-rotation tang. When installing the new lock rings the tang must be installed in the slot and the gap in the lock ring must be positioned as shown. Failure to install correctly may cause the lock ring to come out.



Printed in U.S.A. 91-3 791