

## service bulletin

MERCURY.
PERFORMANCE OUTBOARDS

No. 95-1

## **IMPORTANT NOTICE - 225 REWORK**

The Mercury Marine Outboard Business Unit issued Service Bulletin 94-11 which explains a rework program on the 3.0L 225. Registered owners also received a letter explaining the rework and what procedures they needed to follow. Inadvertently, some registered owners of Hi-Performance 2.5L 225 Pro-Max/Super Magnum models also received letters.

Everyone should be aware that the rework only pertains to the 3.0L 225 and does not pertain to the Pro Max/Super Magnum Series. Any dealers that have ordered kits to rework Hi-Performance 2.5L 225's should return the kits to Mercury Marine, Fond du Lac.

We apologize for any inconvenience this may have caused.

Printed in U.S.A. 95-1 295