

## Fleetmaster Gearcase Forward Gear Backlash Specification

The forward gear backlash was listed incorrectly on several pages (6D-3, 6D-30, 6D-37, 6E-3 and 6E-46) of the 3.0HP EFI, 3.0 Litre Pro Max/Super Magnum service manual 90-849372 797.

The correct Fleetmaster "Forward Gear backlash" of 0.020in. to 0.025in. (0.508 -0.635 mm) is listed under specifications on page 1-3 of the General Information section of the service manual.