

WARRANTY INFORMATION

SERVICE INFORMATION

Correct Spark Plug Gap for 300X Pro Max

Models

All 2001 Model Year 300X Pro Max Engines

Situation

The spark plug gap specification is incorrect on the emissions sticker attached to the engine and in the Operation, Maintenance and Warranty Manual. The incorrect gap is 0.035 in. (0.89 mm), which is too wide.

Correction

The correct spark plug gap for the 300 X Pro Max is 0.025 in. (0.64 mm). When checking or installing spark plugs, set the gap at 0.025 in. (0.64 mm).

