MERCURY Racing	ser	vice	bul	letin
 □ WARRANTY INFORMATION □ PARTS INFORMATION □ PARTS INFORMATION □ Outboard No. 2002-06 				
Circulate to: Sales Manager	Accounting	Service Manager	Technician	Parts Manager

200 XS OptiMax Service Manual Wiring Correction

Models Affected

None. Correction is for the colored wiring diagram in the 200 XS Service Manual.

Situation

A correction to the 200 XS OptiMax Service Manual (90-840421) colored wiring diagram foldout on page 8-3 is needed to correctly depict the wire colors for the Main Power Relay. The Yel/Red wire shown coming from the harness connector should be Yel/Pur.

The black and white wiring diagram on page 2D-19 has the correct wire identification for the main power relay (item #17) and does not require a sticker.

Correction

Place the sticker provided directly above callout number 26 for the Main Power Relay located at the top of the colored wiring diagram.

THE INFORMATION IN THIS DOCUMENT IS <u>CONFIDENTIAL AND PROTECTED BY COPYRIGHT</u> AND IS THE PROPERTY OF MERCURY MARINE. This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.