

Warranty Information

Service Information

Outboard No. 2003-05

Parts Information

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

Connecting Rod Fastener Replacement

Models Affected

- Pro Max/Super Magnum 150-225
- Pro Max 225X
- Pro Max/Super Magnum 300
- Pro Max 300X
- OptiMax 200XS
- OptiMax 250XS

Situation

Previous service literature for the models listed above did not recommend replacement of connecting rod fasteners because replacement was considered common practice.

Correction

Mercury Marine strongly recommends replacing the connecting rod fasteners after each disassembly.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.