

Warranty Information

Service Information

Outboard No. 2004-02

Parts Information

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

## 250XS OptiMax Spark Plug Gap

### Models Affected

All 250XS OptiMax models

### Situation

The 250XS OptiMax Service Manual (90-843128R01) and Mercury Racing Outboard Service Bulletin 2002-07 list an incorrect spark plug gap.

### Correction

The correct spark plug gap is 0.81 mm (0.032 in.). Please make any corrections to existing service literature as needed.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.