

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## Incorrect Spark Plug Listing

### Models Affected

HP525 EFI Serial Numbers 0M950416 to 0M953527

### Situation

The Operation, Maintenance and Warranty Manual shipped with HP 525 EFI Bravo and VI drive engines in the above serial number range have incorrect spark plug information within the Specifications section. The spark plug listed is a colder plug than recommended, and if used, could cause spark plug fouling. Be aware that customers may have installed incorrect spark plugs.

### Correction

Parts department personnel need to be aware that some customers may try to purchase the wrong spark plugs. Also, when servicing HP525 EFI engines in the above serial number range, ensure that the correct spark plugs are installed.

The Operation, Maintenance and Warranty manuals have been updated on MercNet and reflect the correct part number. The spark plug specification is correct in all other Mercury Marine service literature and on the engine identification plate.

### HP525 EFI Spark Plug Specification

Mercury Part Number - 33-810883

NGK Part Number - BPR6ES

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.