

service bulletin

No. 98-20

Service/Repair of Electrical Test Equipment

NOTICE

Revised March 1999. Destroy original December 1998 Bulletin. <u>Changes are underlined</u>.

NOTICE

This bulletin replaces Mariner/Mercury Service Bulletin 95-13 and Force Service Bulletin 95-10.

A reminder, ALL electrical test equipment must be returned to the vendor or repair facility for service repair and/or replacement parts. We encourage contact with the business prior to shipping the unit to obtain shipping, estimate and repair details. The addresses and phone numbers are as follows:

TEST EQUIPMENT

ng Light (self-contained)	99379
i-Meter/DVA91-9	99750
ctach Digital Tachometer	391A1
Tester 91-110)01A2
ital Volt Meter is not serviceable. Purchase a good quality 10 meg ohms impedanc	e. Not

using 10 meg ohms impedance, may not allow EFI tester to normalize.)

VENDOR: Electronic Specialties, Inc.

2449 Pierce Drive

Spring Grove, IL 60081 Telephone: (815) 675-1812

Fax: (815) 675-2905

TEST EQUIPMENT

Tach/Dwell Meter	9	1-59339
Ignition Analyzer	9	1-76032

VENDOR: Merc-O-tronic Service Department

215 Branch

Almont, MI 48003

Telephone: (810) 798-8555 Fax: (810) 798-2222

TEST EQUIPMENT

 Thunderbolt Ignition Analyzer
 91-62563A1

 VOA Meter
 91-62562

 Mark 1 Tester
 91-64645A1

REPAIR: Not Available.

Replacement parts are not available.

TEST EQUIPMENT

Digital Diagnostic Tester (DDT) 91-823686A-2

VENDOR: SPX Corporation

Wayland Facility 801 South Main Wayland, MI 49348 Attn.: Depot Repair

Telephone: (616) 792-0088

Any electrical test equipment received in Fond du Lac, shall be returned to the sender.

TEST EQUIPMENT

VENDOR: Blue-Point Products

5500 SW Arctic Drive Beaverton, OR 97005 Telephone: (800) 547-5740

STICKERS

The Original printing of this bulletin included referral stickers that should have been applied to Mercury/Mariner Service Bulletin 95-13 and/or Force Service Bulletin 95-10.

This service bulletin revision will not include stickers.

Any electrical test equipment received in Fond du Lac, shall be returned to the sender.

Page 2 of 2 MARCH 1999 98-20