



No. 98-21

## Paralift Usage – 3.0 Liter

NOTICE

Revised February 1999. Destroy original January 1999 Bulletin.

## Recommendation

Mercury Hi-Performance and Mercury Outboards does not recommend the use of the Quicksilver Paralift Hydraulic Jack Plate with any 3.0L Mercury Outboard engine. Testing has shown that the paralift can fail when used with these engine packages.

