

Service Bulletin

Jet Drive No. 2009-01

Bulletin No. 2009-06 OEM No. 2009-06

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

New Lanyard Switches

Models Affected

Models Covered

Jet Drive/Mercury/Mariner


New Product Offering

Mercury Marine has created a new waterproof lanyard switch with two different mounting options; flush mount or bezel mount with two inch cut out.

Part number 87-19674Q2 will no longer be available. Please use the chart below to find the correct switch application.

Lanyard Application

Lanyard Application	Mechanical MerCruiser	DTS OB (includes Verado)/MerCruiser and Mechanical Outboard
Single bezel mount	87-19674A06	87-19674A08
Single flush mount	87-19674A05	87-19674A07
Dual bezel mount	Use 87-814324A2 for both applications	87-19674A13 with diode kit
Dual flush mount		87-19674A12 with diode kit
Dual diode kit	Not available at this time	84-898289A72 service replacement only
Triple/quad bezel mount	Not available at this time	87-19674A15 with diode kit
Triple/quad flush mount		87-19674A14 with diode kit
Triple/quad diode kit		84-898289A73 service replacement only



Old vs. new lanyard a - 87-19674Q2 b - New style

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.