



Service Bulletin

Bulletin No. 2009-25

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

2-Stroke Connecting Rod Bearings - 31-17514A1 and 31-17514A2 No Longer Available

Situation

Connecting rod bearings P/N 31-17514A1 and P/N 31-17514A2 are no longer available.

When ordering a replacement set of bearings for the following engines, please order P/N 8M0045428:

Models Covered	Serial Number
Mercury/Mariner 40, 45 Jet, 50, 55, 60 3-cylinder, 849 cc	0D000750 and above
30,40 Jet, 40,50,55,60 3-cylinder, 967 cc	0G531301 and above
V-6 2.0L, 2.4L, and 2.5L 115, 135, 150, 175, 200, 225	All serial numbers All model years
Force 40, 50 2-cylinder 75, 90 3-cylinder 120 4-cylinder	Model years 1996–1999 0E138600 and above
Sport Jet and Jet Drive All HPs All versions	Model year 1996 and newer 0E141089 and above

When ordering a replacement set of bearings for the following engines, please order P/N 8M0045430:

Models Covered	Serial Number
Mercury/Mariner 30, 40 2-cylinder, 644 cc	0G053314 and above

NOTE: One bearing per connecting rod.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.