

Circulate to:     Sales Manager     Accounting     Service Manager     Technician     Parts Manager

## Fuel Primer Bulb Assembly

### Models Affected

Models Covered	Serial Number
Mercury/Mariner/Force All versions except Verado	All
75-115 EFI	1B366823 and below


### Situation

Mercury Marine has released a new fuel primer bulb assembly which is more resistant to fuels containing alcohol and to kinking associated with some rigging applications. If you receive any customer complaints from using the 13330K06 or 13330Q06 primer bulb, replace with the new bulb.

### Part Interchangeability


- P/N 13330K07 supersedes 13330K06
- P/N 13330Q07 supersedes 13330Q06

### Part Identification



**Old primer bulb**  
a - 13330Q06 or 13330K06

The new primer bulb can be identified by the small dot just above the flow directional arrow as shown in the following picture.



**New primer bulb**  
a - 13330Q07 or 13330K07

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.