

service bulletin

TO: SERVICE MANAGER D MECHANICS PARTS MANAGER

No. 92-11

A. TESTING THUNDERBOLT IV HEI IGNITION SYSTEM

This latest test diagram will be added to all Service Manuals at their next update. Use a voltmeter when making these tests. Do not use a test light.



NOTE 1: Early, large ignition modules did not have a replaceable wiring harness.