

TO: SERVICE MANAGER  TECHNICIANS   
PARTS MANAGER

**No. 98-1**

## MCM 3.0L Flame Arrestor Decal

### Models

MCM 3.0L Sterndrive Engine: S/N 0L010042-0L020797

### Situation

The firing order listed on the original flame arrestor decal says 1-4-3-2. This is not correct. The correct firing order is the same as it has been in the past, 1-3-4-2.

### Correction

Order 1 Specification Patch Decal for each engine that you service within the serial number range given. Decal Patch is applied directly on the original flame arrestor decal. Follow directions below.

### Part Required

(1) 37-856602 Decal Patch.

### Warranty

Fill out warranty claim and send it to your normal warranty processing center. More than one engine can be put on the warranty claim if you list the part number, engine model, serial number, warranty code and labor hours for each engine on separate lines on warranty claim.

Warranty Code and Labor:   None                   0.2 Hours.



75824

a - Place Decal Patch Here