

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Service Replacement Joystick

Models Affected

All Mercury MerCruiser models equipped with Axis.

Situation

Joystick part number 879172T62 is no longer available. The service replacement joystick is not a direct backfit because it has a slightly larger body, therefore requiring a larger mounting cutout.

Requirements

If replacing a joystick is required, order both the joystick and the joystick template, available through the EPC. Use the template to enlarge the existing joystick opening. Also, ensure adequate clearance for the new joystick.

Description	Part number
Joystick	879365A21
Joystick template	8M0041782

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.