



service bulletin

No. 93-8

MHP 2.5 Carburetor Jet Change

MODELS:

MHP 2.5 Carb engines

SERIAL NUMBERS

0D 181014 thru 0D935364

Some early 2.5 carburetor engines with non-accelerator style pump carbs may have left the factory with the wrong jets. They were shipped with the jets used in the accelerator style pump carburetors (.076 break-in and .072 run).

The correct jets for the non-accelerator style pump carburetors is **.072 break-in and .068 run**.

Jet	Part Number
.076	1399-3796
.072	1395-6207
.068	1395-6029

Warranty: Submit a warranty claim for 0.5 hours to change jets if required. Refer to this Service Bulletin on the warranty claim.