

Electronic Throttle Position Indicator (P/N 17814A3)

Because of low volumes and inability to obtain quality components, the electronic TPI (P/N 17814A3) is no longer available. If a TPI fails, it will be necessary to purchase a new digital Electronic Control Unit (ECU) which uses an internal TPI. Part numbers for the digital ECU's are as follows.

2.4 litre	11350A40
2.5 litre	11350A49

These parts will not automatically supercede through parts distribution, so please distribute this information to all parts department and service department staff.