

## service bulletin

MERCURY.
PERFORMANCE OUTBOARDS

No. 97-3

**Revised October, 1998** 

## IMPORTANT INFORMATION Paralift Usage With 3.0L Mercury/Mariner Outboard Engines

## Recommendation

Mercury Hi-Performance and Mercury Outboards does not recommend the use of the Quicksilver Paralift Hydraulic Jack Plate with any 3.0L Mercury Outboard engine. Testing has shown that the paralift can fail when used with these engine packages.

## **A** WARNING

Do not install a 3.0L Mercury or Mariner engine on a Quicksilver Paralift Hydraulic Jack Plate. Failure to the Quicksilver Paralift Hydraulic Jack Plate can occur if used with any Mercury or Mariner 3.0L engine.

Printed in U.S.A. 97-3 1098