

**WARRANTY INFORMATION** **SERVICE INFORMATION**

## 2.5 EFI ECM Replacement

### Models Affected

2000 Model Year 2.5 EFI units serial numbers 0G980967 through 0G981545

### Problem

The ECU (Electronic Control Unit) does not accurately monitor engine block pressure.

### Correction

Order a new ECU P/N 858891-14.

Return ECU with a warranty claim and the engine serial number attached to the ECU with either tape or tag to Mercury Racing at the following address.

#### **Return ECU To:**

Mercury Racing  
Attn: Pete Coen  
N7480 County Rd. UU  
Fond du Lac, WI 54935-9585

### Warranty Information

Complete warranty claim listing:

- Engine Serial Number
- Qty. 1 ECU P/N 858891-14
- UFO Code: 731-00
- Flat Rate Code: HI12
- Three Tenths (0.3) hour labor to R & R ECU.