

WARRANTY INFORMATION

SERVICE INFORMATION

Throttle Advance Kit

Models affected: All HP 900SC Engines


Problem

The 900 SC engine may stop running when put into gear if used with a large pitch propeller.

Solution

Mercury Racing has developed a throttle advance kit for the 900 SC that advances the throttles momentarily during shifting. If you have customers that require a kit for their engines, order P/N 845740A3. All engines currently being produced will have this kit installed at the factory.

KIT COMPONENTS



Warranty

Fill out a warranty claim and send it to your normal warranty processing center. More than one engine can be put on the warranty claim if the following information for each engine is on separate lines on the warranty claim.

Serial Number	Engine Model	Part Number	Warranty Code	Labor Hours
---------------	--------------	-------------	---------------	-------------

Warranty Code: **None**

Labor: **1.5 hrs.**