

parts bulletin



No. 97-8

FORCE

STARTER MOTORS FOR OUTBOARD AND L-DRIVE ENGINES 70 THRU 150 HP

SHORT TERM SUPERSESSION

For service replacement of complete starter for 70 thru 125 HP (3 or 4 Cylinder) models, order 50-853869. This replaces 50-F616955 and 50-F616955-1 and 50-819085.

For service replacement of complete starter for 150 HP (5 Cylinder) model only, order 50-819085--1. This replaces 50-F616955 and 50-F616955-1 and 50-819085.

For service replacement of component parts for any starter, use 50-819085 as listed in current parts books and microfiche for your model.

Printed in U.S.A. 97-8 997