

TO: SERVICE MANAGER  MECHANICS   
PARTS MANAGER

No. 92-21

## A. NEW WASTEGATE TO EXHAUST ELBOW FLEX TUBE

### Models

MIE D254 Inboard Engines

### New Flex Tube

If the original flex tube (Figure 1) fails, order a new one (Figure 2).

### Parts

805583 Flex Tube-Wastegate


### Warranty

If the engine is under warranty, fill out a warranty claim and send to your normal processing center.

Warranty Code: None

Labor: 0.30 hour


REPLACE THIS TUBE



71707

Figure 1.

REPLACEMENT TUBE



71762

Figure 2. P/N 805583