



# Service Bulletin

Bulletin No. 2017-08  
OEM No. 2017-07

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## 3.0L Service Longblock Availability

### Models Affected

Description	Serial Number Or Year
3.0L GM New Replacement Longblock Assemblies	All

### Scope

Worldwide

### Situation

General Motors has ceased production of 3.0L longblock assemblies. Part number 864626A01 will become NLA.

Quicksilver now offers four repower options:

1. MerCruiser New Longblock
2. Quicksilver 110 HP Crate Engine
3. Quicksilver 130 HP Crate Engine
4. Quicksilver Plus Series Engine

NLA—GM Longblock Part Number	MerCruiser New Longblock	Quicksilver Crate Engine 3.0L 110 HP	Quicksilver Crate Engine 3.0L 130 HP	Quicksilver Plus Series Engine 3.0L TKS—Engine Only
864626A01 3.0LX 1990–1997 3.0L 1998–2017	8M0128770	8M0123360 (Requires transfer parts)	8M0123362 (Requires transfer parts)	8M0116645 (pending NLA) <b>NOTE: Order 8M0116646 when 8M0116645 becomes fully NLA.</b>

**NOTE:** Refer to the current **Repower Product Guide** for detailed descriptions of MerCruiser new longblock assemblies, Quicksilver Crate Engines, and Quicksilver Plus Series Engines.

**NOTE:** Longblock services Volvo sterndrive and LW6 industrial engines.

**IMPORTANT:** Some internal components are not interchangeable between part numbers 8M0116645 and 8M0116646.

**IMPORTANT:** Refer to the engine specifications decal and the Repower Reference Manual included with each engine for ignition timing, engine/drive alignment, and oil system priming information.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.