Motor Guide MARINE

THRUSTER

service bulletin

☐ WARRANTY INFORMATION☑ PARTS INFORMATION	SEF	RVICE INFORMATIO	DN Bul	letin No. 2002-23
Circulate to: Sales Manager A	ccounting	Service Manager	Technician	Parts Manager

Terminal Connector No Longer Available (NLA)

Situation

Part Number MPM16001 is no longer available (NLA). This terminal was used in applications from 22 gauge to 10 gauge.

Correction

Replace with the proper terminals for the correct wire gauge using the chart below.


NOTE: Priced and packaged in the indicated multi-pack quantity.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Parts Required

P/N	Wire Gauge	Blade Width	Multi-pack Quantity
67-851760	0.3 - 0.8 mm ² (22-18 gauge)	4.7 mm (.187 in.)	25 pack
67-851761	0.3 - 0.8 mm ² (22-18 gauge)	4.7 mm (.187 in.)	100 pack
67-851762	0.3 - 0.8 mm ² (22-18 gauge)	6.4 mm (.250 in.)	25 pack
67-851763	0.3 - 0.8 mm ² (22-18 gauge)	6.4 mm (.250 in.)	100 pack
67-851764	1.0 - 2.0 mm ² (16-14 gauge)	4.7 mm (.187 in.)	25 pack
67-851765	1.0 - 2.0 mm ² (16-14 gauge)	4.7 mm (.187 in.)	100 pack
67-851766	1.0 - 2.0 mm ² (16-14 gauge)	6.4 mm (.250 in.)	20 pack
67-851767	1.0 - 2.0 mm ² (16-14 gauge)	6.4 mm (.250 in.)	100 pack
67-851768	3.0 - 5.0 mm ² (12-10 gauge)	6.4 mm (.250 in.)	20 pack
67-851769	3.0 - 5.0 mm ² (12-10 gauge)	6.4 mm (.250 in.)	75 pack



a - Blade width

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Page 2 of 2 DECEMBER 2002 2002-23