



# parts bulletin



No. 97-9

## POWER STEERING ON 1998 MODEL YEAR PART NUMBERS

17443A 2

17443A 3

17443A 8

17443A11

17443A15

An interference exists between the power steering actuator bracket and the new style clamp brackets that are installed on 1998 model year outboards (75 HP - 250 HP). Therefore, Quicksilver outboard power steering will **not** fit properly on 1998 model year product. **Do not** attempt to install Quicksilver outboard power steering on 1998 model outboards.

While these kits are no longer available (NLA) from Quicksilver, the potential exists for kits from dealer inventories to be installed into these applications, or for kits to be transferred from one outboard to another.